



Wall of Shame

October 9, 2012

S#	WM Mfg. Plant Location	PO Number	Part Number/ Program	Customer	Customer QN Ref. #	Containment Location(s)	Containment / Sorting Company	Description of Quality Issue	Containment Cost Weekly	Controlled Containment Start Date	Controlled Containment End Date	Target	Note
76	INDY	12430	Kuga 4way	Magna Spain, Valencia		Magna Spain, Valencia	KH Vives	Chuck, missing bushing	260.00	October 8, 2012	October 9, 2012	October 9, 2012	An old issue requires containment due to slow shipment by sea.
80*	WMPI	12425	D258 1r 4way	Lear Hammond	5905	Lear Hammond	QT1	Foam Read Through	1,440.00	October 8, 2012	October 12, 2012	October 12, 2012	PO was issued by Mike Giroux. Defective Buns supplied by G&R 3
81*	WMM	12432	U502 3rd	Lear Hammond	5869, 5885	Lear Hammond	QT1	Not proper function	2,675.00	October 8, 2012	October 12, 2012	October 12, 2012	Root Cause Analysis TBD
82*	G&R 3	12442	WK Armrest	Magna Detroit	1009122	Magna Detroit	QT1	indented cup holder	510.00	October 9, 2012	October 11, 2012	October 11, 2012	Hawk Plastics to be debited for most associated costs.

4,885.00