

main at the Letter paper size form.	Ford GPPSS1 The original copy of this document shall remain at the supplier's focation while the part is eather toward the component of the part is eather than the control of the part is eather than the part is eather than the control of the part is eather than the part is eather than the control of the part is eather than the c
Interim Status (to be completed by the Organization) Engineering Authorization Alert, Temp. PCM, TPD Number Description: (noomplete PPAP Requirements)	Phased PPAP Warrant Status: Customer Signatus Phint Name Sy ed Africans and is considered incomplete until all PPAP requirements are satisfied.
O № O n/a Date 18-Apr-08 519-737-7155 Fax No. 519-737-7102 achau@windsomnachine.com	is each Customer Tool properly tagged and numbered? Organization Authorized Signature Print Name Ana Chau Phone No. 519-737-7155 Title PPAP Coordinator Email achau@winds
appearance criteria statistical process package Required). Required). The statistical process package are statistical process package are statistical process all coeffic requirements. I further affirm that these production streams. I also certify that toled any exceptions from this declaration below.	SUBMISSION RESULTS The results for dimensional measurements, material and functional tests appearance criteria statistical process. These results meat all design requirements. Yes No. (If 'No' - Explanation Required). Mod / Cavity / Production Process(es) Yeself, Weld, Bolt Assembly DECLARATION DECLARATION DECLARATION The samples represented by this warrant are representative of our perits which were made by a process which meets all Production Part Approval Process Manual 4th Edition requirements including all Ford-specific requirements. I further affirm that these samples were produced at the production rate of 125 / 8 hours using 1 production streams. I also certify that documented evidence of such compliance is on file and is available for review. I have noted any exceptions from this declaration below.
oval Report) submitted to customer. o customer. supplier's manufacturing location.	REQUESTED SUBMISSION LEVEL (Check one) O Level 1 - Warrant only (and for designated appearance items, an Appearance Approval Report) submitted to customer. O Level 2 - Warrant with product samples and similed supporting data submitted to customer. O Level 3 - Warrant with product samples and complete supporting data submitted to customer. O Level 3 - Warrant and other requirements as defined by customer. O Level 3 - Warrant with product samples and complete supporting data reviewed at supplier's manufacturing location.
52343862 es O No ® ry'a Change to Optional Construction or Material Supplier or Material Source Change Change In Part Processing Parts produced at Additional Location Other - please specify below	sion and date transmitted marking codes? O Y ment, or additional
CUSTOMER SUBMITTAL INFORMATION Ford Motor Company Customer NameDivision George Berletic / GKB5 BuyerBuyer Code TF7 Superduty Application © Yes O No	ORGANIZATION MANUFACTURING INFORMATION Windsor Machine & Stamping LTD / W739J Organization Name and Supplier/vendor Code 26655 Northline Road Street Address Taylor, Michigan 48180 US Taylor, Michigan Postal code County MATERIALS REPORTING Has customer-required Substances of Concern information been reported? Schmilted Authors or other restricts formatic
Cust. Part Number 7C34-5A246-AE Organization Part Number 7C34-5A246-AE Dated 4/18/07 Dated N/A Weight (rg) 1.7150 KG Level Dated Dated	Purct